

# 3BHK T1 Window Glass Work Done

Timestamp camera




06/06/2023 02:57 pm GMT+05:30

28.44573° N 76.98376° E

# 3BHK T2 Window Glass Work Done

Timestamp camera




06/06/2023 02:54 PM GMT+05:30

28.44583° N 76.98417° E

# 3BHK T3 Window Glass Work Done

Timestamp camera



06/06/2023 02:54 PM GMT+05:30

28.44574° N 76.98452° E

# 3BHK T4 Window Glass Work Done

Timestamp camera



06/06/2023 12:43 PM GMT+0528044552° N 76.98463° E

2BHK Tower 2A/T5 External paint work in progress.



2BHK Tower 2B/T6 internal & External paint work in progress.



# 2BHK Tower 2C/T7 External paint work in progress.



# 2BHK Tower 2D/T8 Parapet Work in Progress..





# 2BHK 2E/T9 Columns Up To 11<sup>th</sup> Floor lvl.



06/06/2023 12:40 PM GMT+05:30 4518° N 76.98576° E

# Tower 2BHK 2F/T10 Terrace Done

Timestamp camera



06/06/2023 12:42 PM GMT+05:30 45° 19' N 76.98486° E

# 2BHK Tower 2G/T11 Parapet Work in Progress.

Timestamp camera

06/06/2023 12:39 PM GMT+05



# UG Tank Work in Progress



# Tile Work in Progress

